


LIN and BSS Voltage Regulators

IB0839



Voltage Regulator - Bosch Replacement

Protocol : **LIN** ID : **24** COM Speed (bps) : **19200**

Replaces : **Bosch 0 272 220 809, 0 272 220 839, F 00M 346 151, Original Reference Number ARB0808**

Unit-Numbers : **Bosch 0 125 711 030, 0 125 711 055, 0 125 711 075, 0 125 711 076, 0 125 711 080, 0 125 711 093, 0 125 711 094, 0 125 711 163, 0 125 711 164; Mercedes-Benz 000 906 00 22, 000 906 18 22, 000 906 20 03, 000 906 76 02 KZ, 000-906-19-03, 0009065501, A 000 906 00 22, A 000 906 18 22, A 000 906 20 03, A 000 906 76 02 KZ, A-000-903-00-22, A-000-906-19-03, A0009065501; Nissan, Infiniti 23100 4HH3A**

IB203




Voltage Regulator - Bosch Replacement

Protocol : **BSS** ID : **8** COM Speed (bps) : **1200**

Replaces : **Bosch F 00M 255 203**

Unit-Numbers : **BMW 12-31-7-507-741, 12-31-7-507-995, 12-31-7-509-096, 12-31-7-509-109, 12-31-7-523-605, 12-31-7-526-285; Bosch 0 122 0AA 090, 0 122 0AA 2B0**

IB262




Voltage Regulator - Bosch Replacement

Protocol : **BSS** ID : **20** COM Speed (bps) : **1200**

Replaces : **BMW 12-31-7-505-922, 12-31-7-523-059, 12-31-7-540-656, Bosch F 00M 145 262, F 00M 145 285, F 00M 145 312, F 00M 145 655, F 00M 145 880, F 00M A45 221**

Unit-Numbers : **BMW 12-31-7-505-897, 12-31-7-516-101, 12-31-7-516-723, 12-31-7-521-384, 12-31-7-521-490, 12-31-7-521-491, 12-31-7-532-965, 12-31-7-532-966, 12-31-7-532-969, 12-31-7-533-270, 12317516102; Bosch 0 124 515 051, 0 124 515 098, 0 124 525 045, 0 124 525 059, 0 124 525 561, 0 399 604 014**

IB293




Voltage Regulator - Bosch Replacement

Protocol : **BSS** ID : **12** COM Speed (bps) : **1200**

Replaces : **Bosch F 00M 144 147, F 00M 145 272, F 00M 145 293, F 00M 145 367, F 00M 145 385, Mercedes-Benz 003-154-37-06, 003-154-58-06**

Unit-Numbers : **Bosch 0 124 515 088, 0 124 515 198, 0 124 615 022, 0 124 615 028, 0 124 625 017, 0 124 625 022; Marelli 063536150280; Mercedes-Benz 012-154-06-02, 013-154-21-02, 271 154 09 02, 271-154-02-02, 271-154-06-02, 271-154-08-02, 271-154-08-02, 271-154-10-02, 628-154-01-02, A 271 154 09 02, A013-154-21-02, A2711540202, A2711540802, A2711540802, A2711541002, A6281540102**

IB321



Voltage Regulator - Bosch Replacement


Protocol : **BSS** ID : **9** COM Speed (bps) : **1200**

Replaces : **Bosch F 00M 144 131, F 00M 144 185, F 00M 144 188, F 00M 144 193, F 00M 145 301, F 00M 145 303, F 00M 145 304, F 00M 145 321, F 00M 145 335, F 00M 145 858**

Unit-Numbers : **Bosch 0 124 325 139, 0 124 325 176, 0 124 325 186, 0 124 425 011, 0 124 425 012, 0 124 425 013, 0 124 425 018, 0 124 425 029, 0 124 425 034, 0 124 425 037, 0 124 425 038, 0 124 425 039, 0 124 425 042, 0 124 425 045, 0 124 425 046, 0 124 425 047, 0 124 425 069, 0 124 425 070, 0 124 425 071, 0 124 425 074, 0 124 425 075, 0 124 425 107, 0 124 425 108, 0 124 425 109, 0 124 425 110, 0 124 425 111, 0 124 425 114, 0 124 425 115, 0 124 525 053, 0 124 525 069, 0 124 525 078, 0 124 525 081, 0 124 525 108, 0 124 525 138, 0 124 525 139, 0 124 525 151, 0 124 525 534, 0 124 525 538; Nissan, Infiniti 23100 0003R, 23100-0012R, 23100-003R, 23100-8578R; F 042 301 225; Renault 23 10 006 46R, 23100-0012R, 23100-003R, 7701475896, 7701476812, 7711368380, 7711497091, 80-00-429-905, 82 00 323 137, 82 00 660 025, 82 00 660 034, 82 00 660 034, 8200 510 409, 8200262318, 8200269454, 8200269463, 8200323127, 8200325820, 8200325823, 8200356669, 8200360480, 8200360481, 8200390675, 8200390676, 8200429898, 8200429905, 8200429905, 8200459711, 8200474219, 8200518409, 8200518409, 8200660033, 8200660037, 8200660041, 8200660043, 8200660043, 8200726639, 8200737574**

LIN and BSS Voltage Regulators

IB5289




Voltage Regulator - Bosch Replacement

Protocol : **BSS** ID : **12** COM Speed (bps) : **1200**

Replaces : **BMW** 12 31 7 512 163, 12 31 7 523 065, 12 31 7 540 655, 12 31 7 541 853, 7 512 163, 7 523 065, 7 540 655, **Bosch** F 00M 145 258, F 00M 145 268, F 00M 145 289, F 00M 145 316, F 00M 145 656, F 00M 145 882, F 00M A45 223

Unit-Numbers : **BMW** 12 31 7 521 488, 12 31 7 521 489, 12 31 7 521 489, 12 31 7 532 964, 12 31 7 532 968, 12 31 7 533 272, 12-31-4-456-281, 12-31-7-505-896, 12-31-7-512-151, 12-31-7-516-098, 12-31-7-516-721, 12-31-7-516-722, 12317521383; **Bosch** 0 124 325 030, 0 124 325 062, 0 124 325 072, 0 124 325 087, 0 124 325 099, 0 124 325 116; **Steyr** 7532968

IB5290




Voltage Regulator - Bosch Replacement

Protocol : **BSS** ID : **22** COM Speed (bps) : **1200**

Replaces : **Bosch** F 00M 145 308, F 00M 145 322

Unit-Numbers : **Bosch** 0 124 525 063; **Citroen** 5705CA, 9646452480, 9649846780; **Peugeot** 5705CA; **PSA Peugeot Citroen** 96464524

IB5302



Voltage Regulator - Bosch Replacement

Protocol : **BSS** ID : **20** COM Speed (bps) : **1200**

Replaces : **Bosch** F 00M 145 651, F 00M A45 302

Unit-Numbers : **Bosch** 0 124 525 106, 0 124 525 107; **Porsche** 997-603-022-00, 997-603-022-01, 997-603-022-02, 997-603-022-03, 997-603-022-04, 997-603-022-05, 997-603-022-EX

IB5378




Voltage Regulator - Bosch Replacement

Protocol : **LIN** ID : **32** COM Speed (bps) : **19200**

Replaces : **Bosch** F 00M 144 158, F 00M 145 310, F 00M 145 378, F 00M 145 852, F 00M 145 886, **Mercedes-Benz** 003 154 44 06, 003 154 62 06, 003-154-75-06, 004-154-01-06, A 003 154 44 06, A 003 154 62 06, A-003-154-75-06, A-004-154-01-06

Unit-Numbers : **Bosch** 0 124 625 023; **Chrysler** 68011841AA, 68011841AB; **Mercedes-Benz** 272-154-01-02, A272-154-01-02

IB5379



Voltage Regulator - Bosch Replacement

Protocol : **LIN** ID : **88** COM Speed (bps) : **9600**


Replaces : **Bosch** F 00M 145 311, F 00M 145 379, F 00M A45 212

Unit-Numbers : **Bosch** 0 124 525 060, 0 124 525 061, 0 124 525 521, 0 124 525 522, 0 124 625 024, 0 124 625 025; 89213652, 9213652, SB289; **Volvo** 30658065, 30658084, 30658085, 30658086, 30667787, 30667892, 30667893, 30667894, 36050269, 8603262, 8603262-0, 8603263, 8603263, 8603264, 8603265-0

LIN and BSS Voltage Regulators

www.waiglobal.com

IB5881



Voltage Regulator - Bosch Replacement

Protocol : **BSS** ID : **31** COM Speed (bps) : **1200**

Replaces : **BMW 12 31 7 540 657, 12 31 7 542 530, 7 540 657, Bosch F 00M 145 317, F 00M 145 881, F 00M A45 222**

Unit-Numbers : **BMW 12-31-4-487-081, 12-31-4-487-081, 12-31-7-542-529, 12-31-7-542-529, 12-31-7-543-083, 12-31-7-543-083; Bosch 0 124 525 083, 0 124 525 524; 302009RI, 89212506**

IB6020




Voltage Regulator - Bosch Replacement

Protocol : **LIN** ID : **48** COM Speed (bps) : **19200**

Replaces : **Bosch F 00M 346 006, F 00M 346 020, F 00M 346 036, F 00M 346 048, F 00M 346 081, F 00M 349 831, WG1776028**

Unit-Numbers : **Bosch 0 120 000 025, 0 121 813 001, 0 121 813 002, 0 121 813 003, 0 121 813 005, 0 121 813 006, 0 121 813 014, 0 121 813 020, 0 121 813 023, 0 121 813 101, 0 121 813 102, 0 121 813 103, 0 121 813 105, 0 121 813 106, 0 121 813 114, 0 121 813 120, 0 121 813 123; CE Niehoff 4048; Chrysler 68011843AA, 68011843AC, 68011843AD; Mercedes-Benz 000-906-02-00, 013 154 99 02, 013-154-05-02, 013-154-06-02, 013-154-09-02, 013-154-55-02, 013-154-99-02, 014-154-13-02, 629-150-04-50, A 013 154 99 02, A000-906-02-00, A013-154-09-02, A0131540502, A0131540602, A0131545502, A014-154-13-02, A629-150-04-50; 68011 843AC**

IB6024




Voltage Regulator - Bosch Replacement

Protocol : **BSS** ID : **6** COM Speed (bps) : **1200**

Replaces : **BMW 12-31-7-552-817, 12-31-7-561-924, 12-31-7-561-939, Bosch F 00M 346 013, F 00M 346 024, F 00M 346 033, F 00M 346 089**

Unit-Numbers : **BMW 12-31-7-542-351, 12-31-7-550-469, 12-31-7-550-968, 12-31-7-551-256, 12-31-7-551-256, 12-31-7-555-926, 12-31-7-558-219, 12-31-7-558-220, 12-31-7-560-985, 12-31-7-560-986, 12-31-7-582-699; Bosch 0 121 715 012, 0 121 715 016, 0 121 715 017, 0 121 715 018, 0 121 715 112, 0 121 715 112, 0 121 715 116, 0 121 715 117, 0 121 715 118, 4884; Marelli 063537151120; 7551256-07; Steyr 7551256**

IB6037




Voltage Regulator - Bosch Replacement

Protocol : **LIN** ID : **56** COM Speed (bps) : **19200**

Replaces : **Bosch F 00M 346 008, F 00M 346 021, F 00M 346 037, F 00M 346 047, F 00M 346 080**

Unit-Numbers : **Bosch 0 121 715 006, 0 121 715 007, 0 121 715 011, 0 121 715 014, 0 121 715 015, 0 121 715 029, 0 121 715 107, 0 121 715 114, 0 121 715 115, 0 121 715 129; Marelli 063537151140; Mercedes-Benz 000-906-05-06, 013 154 35 02, 013-154-35-02, 013-154-56-02, 013-154-64-02, 013-154-70-02, 013-154-90-02, 156-154-01-02, 272-154-08-02, A 013 154 35 02, A-000-906-05-06, A-013-154-56-02, A013-154-64-02, A013-154-70-02, A013-154-90-02, A0131543502, A13-154-70-02, A1561540102, A2721540802; Steyr 013-154-70-02**

IB6066



Voltage Regulator - Bosch Replacement

Protocol : **BSS** ID : **1** COM Speed (bps) : **1200**


Replaces : **BMW 12-31-7-577-245, Bosch F 00M 346 061, F 00M 346 066**

Unit-Numbers : **BMW 12-31-7-575-650, 12-31-7-575-872, 12-31-7-575-873, 12-31-7-576-550; Bosch 0 121 615 027, 0 121 615 127; Citroen 5702L3; ADB111104; PSA Peugeot Citroen 5705 KF; Steyr 7575650**

LIN and BSS Voltage Regulators

www.waiglobal.com

IB6056



Voltage Regulator - Bosch Replacement


Protocol : **LIN** ID : **88** COM Speed (bps) : **9600**

Replaces : Bosch F 00M 346 005, F 00M 346 019, F 00M 346 056, F 00M 346 097, F 00M 346 131, F 00M 346 166,

Volvo 30667453

Unit-Numbers : Bosch 0 120 000 003, 0 120 000 029, 0 121 615 005, 0 121 615 006, 0 121 615 007, 0 121 615 008, 0 121 615 009, 0 121 615 014, 0 121 615 021, 0 121 615 028, 0 121 615 105, 0 121 615 106, 0 121 615 107, 0 121 615 108, 0 121 615 109, 0 121 615 114, 0 121 615 121, 0 121 615 128, 0 121 715 002, 0 121 715 008, 0 121 715 024, 0 121 715 032, 0 121 715 079, 0 121 715 102, 0 121 715 108, 0 121 715 124, 0 121 715 132, 0 121 715 179, 0 125 711 002, 0 125 711 014, 0 125 711 023, 0 125 711 040, 0 125 711 047, 0 125 711 048, 0 125 711 053, 0 125 711 158, 0 125 711 179, 0 125 811 002, 0 125 811 005, 0 125 811 019, 0 125 811 020, 0 125 811 109, 0 125 811 110, F 000 BL0 639; Ford 1376501, 1379699, 1379700, 1379701, 1387927, 1388002, 1388003, 1388004, 1420871, 1425016, 1435647, 145494, 1455494, 1458640, 1469391, 1469400, 1506300, 1541451, 1757316, 1790382, 1790384, 1790385, 1790386, 1791839, 1791840, 5215796, 5287955, 6G9N-10300-ABA, 6G9N-10300-ABB, 6G9N-10300-ABC, 6G9N-10300-ADA, 6G9N-10300-ADB, 6G9N-10300-DA, 6G9N-10300-DB, 6G9N-10300-DC, 6G9N-10300-DD, 6G9N-10300-HA, 6G9N-10300-HB, 6G9N-10300-HC, 6G9N-10300-HD, 6G9N-10300-JB, 6G9N-10300-JD, 6G9N-10300-UA, 6G9N-10300-UB, 6G9N-10300-UC, 6G9N-10300-UD, 6G9N-10300-XA, 6G9N-10300-XB, 6G9N-10300-XC, 6G9N-10300-YC, 6G9N-10399-HB, 6M5T-10300-SA, 7G9N-10300-EA, 8V21-10300-BB, AB39-10300-AD, AB39-10300-AE, AB39-10300-AF, AB39-10300-AFFC, AM5T-10300-SA, RE6G9N-10300-ABC, RE6G9N-10300-ADB, RE6G9N-10300-DD, RE6G9N-10300-HD, RE6G9N-10300-UD, RE6G9N-10300-XC, RE7G9N-10300-EA; Ford Engineering 2099437, 2099442, 2099447, 2099451, 2099465, 2099469, 2099471, 6G9J 10300 AA, 6G9J 10300 ADA, 6G9J 10300 DA, 6G9J 10300 HA, 6G9J 10300 UA, 6G9N-ABA, 6G9N-ABB, 6G9N-ABC, 6G9N-HA, 6G9N-HB, 6G9N-HC, 6G9N-HD, 6M5J 10300 SA, 7G9J 10300 EA; Land Rover LR001200, LR002899; Marelli 063536151210; Mazda Y406-18-300; 89213012; Volvo 30659131, 30659136, 30659341, 30667018, 30667118, 30667119, 30667295, 30667524, 30667525, 30667896, 3077311-0, 30773111, 30782032, 30782032-0, 30795169, 30795210, 31285627, 31285628, 31288879, 31288880, 36000037, 36000038, 36000207, 36000207-0, 36000220, 36000223, 36000613, 36000791, 36000791-0, 36000798, 36001105, 36001105-0, 36001341, 36001341-0, 36001454, 36001497, 36001497-0, 36002176, 36002176-0, 36012618, 36012618-0, 36012619, 36012619-0, 8603388, 8603605, 8603605-0, 8603898, 8603898-0, 8697585

IB6067




Voltage Regulator - Bosch Replacement

Protocol : **LIN** ID : **24** COM Speed (bps) : **19200**

Replaces : Bosch 0 272 220 804, 0 272 220 824, 0 272 220 854

Unit-Numbers : Audi, Volkswagen 03L-903-023K, 03L-903-023KX, 04B 903 023D, 04B 903 023DX, 04B 903 024, 04B 903 024X, 04B-903-023B, 04B-903-023BX, 04C-903-023L, 04C-903-023LX, 04C-903-023T, 04C-903-023TX, 04E 903 023 B, 04E 903 024 Q, 04E 903 024 QX, 04E-903-023B, 04E-903-023J, 04E-903-024S, 04E-903-024SX, 04L 903 023K, 04L 903 023KX, 04L 903 024 T, 04L 903 024 TX, 04L-903-024S, 04L-903-024SX, 06J-903-023A, 06J-903-023AX, 06J-903-023G, 06J-903-023GX, 06K 903 024 A, 06K 903 024 AX, 07K 903 024, 07K 903 024X, 305 925 140; Bosch F 000 BL0 800, F 000 BL0 803, F 000 BL0 805, F 000 BL0 818, F 000 BL0 829, F 000 BL0 830, F 000 BL0 8A0, F 000 BL0 8C8, F 000 BL0 8E1, F 000 BL0 8E2, F 000 BL0 8F1, F 000 BL0 8F2, F 000 BL0 8F7, F 000 BL0 8F8, F 000 BL0 8G3, F 000 BL0 8G4, F 000 BL0 8G7, F 000 BL0 8G8, F 000 BL0 8J1, F 000 BL0 8J2, F 000 BL0 8J3, F 000 BL0 8J4, F 000 BL0 8J5, F 000 BL0 8J6, F 000 BL0 8J7, F 000 BL0 8J8, F 000 BL0 8K1, F 000 BL0 8K2, F 000 BL0 8M5, F 000 BL0 8M6, F 000 BL0 8M7, F 000 BL0 8M8, F 000 BL0 8P1, F 000 BL0 8P2, F 000 BL0 8P3, F 000 BL0 8P4; Lucas LRA03658; 9090778F, 931167, EAA-224087, EAA-224089

IB6132




Voltage Regulator - Bosch Replacement

Protocol : **BSS** ID : **12** COM Speed (bps) : **1200**

Replaces : Bosch F 00M 144 108, F 00M 144 132, F 00M 144 156, F 00M 145 292, F 00M 145 374, F 00M 145 884, Mercedes-Benz 003-154-59-06, 003-154-71-06, 004-154-03-06, A003-154-59-06, A003-154-71-06, A004-154-03-06

Unit-Numbers : Bosch 0 124 625 014, 0 124 625 015, 0 124 625 045, 0 986 048 550, 0 986 048 557; Marelli 063536250450; Mercedes-Benz 012-154-99-02, 013-154-00-02, A0131540002, A0141540702

IB6135



Voltage Regulator - Bosch Replacement

Protocol : **BSS** ID : **7** COM Speed (bps) : **1200**


Replaces : Bosch F 00M 346 135

Unit-Numbers : BMW 12-31-7-604-782, 12-31-7-613-445; Bosch 0 125 711 011, 0 125 711 078

LIN and BSS Voltage Regulators

www.waiglobal.com

IB6139



Voltage Regulator - Bosch Replacement

Protocol : **LIN** ID : **40** COM Speed (bps) : **19200**

Replaces : **Audi, Volkswagen 03G 903 097, 059 903 803 F, Bosch F 00M 346 044, F 00M 346 092, F 00M 346 139**

Unit-Numbers : Audi, Volkswagen 03G-903-016L, 03G-903-016LX, 03G-903-016N, 03G-903-016NX, 03L-903-023D, 03L-903-023DX, 059 903 016 P, 059 903 016 PX, 059-903-016P, 059-903-016PX, 059-903-018E, 059-903-018EX, 059-903-018K, 06E-903-016T, 06E-903-016TX, 06E-903-018H, 06E-903-018HX, 079-903-015D;

Bosch 0 121 715 030, 0 121 715 041, 0 121 715 049, 0 121 715 050, 0 121 715 051, 0 121 715 071, 0 121 715 076, 0 121 715 077, 0 121 715 078, 0 121 715 080, 0 121 715 149, 0 121 715 150, 0 121 715 151, 0 121 715 171, 0 121 715 176, 0 121 715 177, 0 121 715 178, 0 121 715 180; Marelli 063537151710

IB6150




Voltage Regulator - Bosch Replacement

Protocol : **LIN** ID : **8** COM Speed (bps) : **19200**

Replaces : **Bosch F 00M 144 150, F 00M 145 323, F 00M 145 380, F 00M 145 665, F 00M 145 698, Mercedes-Benz 003-154-72-06, 003-154-96-06, A 003-154-72-06, A 003-154-96-06**

Unit-Numbers : Bosch 0 124 325 169, 0 124 325 170; Mercedes-Benz 646-154-00-02, A6461540002

IB6165



Voltage Regulator - Bosch Replacement

Protocol : **LIN** ID : **88** COM Speed (bps) : **9600**

Replaces : **Bosch F 00M 346 012, F 00M 346 023, F 00M 346 057, F 00M 346 074, F 00M 346 098, F 00M 346 165**

Unit-Numbers : Bosch 0 120 000 003, 0 120 000 029, 0 121 615 005/006/007/008, 0 121 615 009/014/021/028/105/106/107/108/109/114/121/128, 0 121 715 002/008/024/032/079/102/108/124/132/179, 0 125 711 002/014/023/040/047/048/053/158/179, 0 125 811 002/005/019/020/109/110, F 000 BL0 639; Ford 1376501, 1379699, 1379700, 1379701, 1387927, 1388002, 1388003, 1388004, 1420871, 1425016, 1435647, 145494, 1455494, 1458640, 1469391, 1469400, 1506300, 1541451, 1757316, 1790382, 1790384, 1790385, 1790386, 1791839, 1791840, 5215796, 5287955, 6G9N-10300-ABA/ABB/ABC/ADA/ADB/DA/DB/DC/DD/HA/HB/HC/HD/JB, 6G9N-10300-JD/UA/UB/UC/UD/XA/XB/XC/YC, 6G9N-10399-HB, 6M5T-10300-SA, 7G9N-10300-EA, 8V21-10300-BB, AB39-10300-AD/AE/AF/AFFC, AM5T-10300-SA, RE6G9N-10300-ABC/ADB/DD/HD/UD/XC, RE7G9N-10300-EA; Ford Engineering 2099437, 2099442, 2099447, 2099451, 2099465, 2099469, 2099471, 6G9J 10300 AA / ADA / DA / HA / UA, 6G9N-ABA / ABB / ABC / HA / HB / HC / HD, 6M5J 10300 SA, 7G9J 10300 EA; Land Rover LR001200, LR002899; Marelli 063536151210; Mazda Y406-18-300; 89213012; Volvo 30659131, 30659136, 30659341, 30667018, 30667118, 30667119, 30667295, 30667524, 30667525, 30667896, 3077311-0, 30773111, 30782032, 30782032-0, 30795169, 30795210, 31285627, 31285628, 31288879, 31288880, 36000037, 36000038, 36000207, 36000207-0, 36000220, 36000223, 36000613, 36000791, 36000791-0, 36000798, 36001105, 36001105-0, 36001341, 36001341-0, 36001454, 36001497, 36001497-0, 36002176, 36002176-0, 36012618, 36012618-0, 36012619, 36012619-0, 8603388, 8603605, 8603605-0, 8603898, 8603898-0, 8697585

IB6197



Voltage Regulator - Bosch Replacement

Protocol : **LIN** ID : **24** COM Speed (bps) : **19200**


Replaces : **Audi, Volkswagen 06E 903 803 F, 07K-903-803, Bosch F 00M 144 151, F 00M 144 180, F 00M 144 197, F 00M 145 662, F 00M 145 851, Mercedes-Benz 003-154-84-06, 003-154-93-06, 003-154-97-06, A-003-154-93-06, A-003-154-97-06, A003-154-84-06**

Unit-Numbers : Audi, Volkswagen 03C-903-023S, 03C-903-023SX, 03C-903-025F, 03C-903-025FX, 03C-903-025J, 03C-903-025JX, 03G-903-016B, 03G-903-016BX, 03G-903-016E, 03G-903-016EX, 03L-903-023, 03L-903-023X, 03L-906-023, 059-903-016E, 059-903-016EX, 059-903-019A, 059-903-019B, 06E-903-016N, 06E-903-016NX, 06H-903-016L, 06H-903-016L, 06H-903-016LX, 06H-903-016LX, 07K-903-023F, 07K-903-023FX; Bosch 0 124 225 058, 0 124 225 064, 0 124 225 113, 0 124 225 114, 0 124 225 115, 0 124 225 116, 0 124 225 171, 0 124 225 187, 0 124 225 188, 0 124 225 200, 0 124 225 215, 0 124 225 220, 0 124 225 223, 0 124 225 226, 0 124 225 228, 0 124 225 530, 0 124 225 531, 0 124 225 542, 0 124 225 543, 0 124 225 544, 0 124 225 547, 0 124 225 548, 0 124 615 042, 0 399 604 018, 0 399 604 031, 0 399 604 033, 0986083140; Chrysler 04862629AA, 4862629AA; Marelli 063535255420; Mercedes-Benz 000 906 12 00 80, 000 906 12 02, 000-906-03-22, 000-906-24-00, 013-154-58-02, 013-154-63-02, 013-154-69-02, A 000 906 12 00 80, A 000 906 12 02, A000-906-24-00, A013-154-58-02, A013-154-63-02, A013-154-69-02

LIN and BSS Voltage Regulators

www.waiglobal.com

IB678




Voltage Regulator - Bosch Replacement

Protocol : **BSS** ID : **20** COM Speed (bps) : **1200**

Replaces : **BMW 12 31 7 515 811, XX XX 7 515 811, Bosch F 00M 145 278, F 00M 145 678, F 00M A45 218**

Unit-Numbers : **BMW 12-31-7-519-721, 12-31-7-519-723, 12-31-7-521-135, 12-31-7-541-694, 12-31-7-541-696, 12-31-7-546-284, 12-31-7-546-285; Bosch 0 124 525 026, 0 124 525 080, 0 124 525 523; Marelli 063535250260**

IB6866



Voltage Regulator - Bosch Replacement

Protocol : **BSS** ID : **31** COM Speed (bps) : **1200**

Replaces : **Bosch F 00M 145 866, F 00M A45 220**

Unit-Numbers : **BMW 12-31-7-794-970, 12-31-7-806-779; Bosch 0 124 525 126, 0 124 525 526**

IB823




Voltage Regulator - Bosch Replacement

Protocol : **LIN** ID : **88** COM Speed (bps) : **19200**

Replaces : **Bosch 0 272 220 823**

Unit-Numbers : **Bosch 0 125 711 041, 0 125 711 042, 0 125 812 009, 0 125 812 012, 0 125 812 037, 0 125 812 038, 0 125 812 071, 0 125 812 072, 0 125 812 073, 0 125 812 074, 0 125 812 075, 0 125 812 076; Volvo 30644945, 30659580, 31419101, 31489212, 36002812, 36002812-0, 36011427, 36011427-0, 36012360, 36012360-0, 36012474, 36012474-0**

IB827




Voltage Regulator - Bosch Replacement

Protocol : **LIN** ID : **48** COM Speed (bps) : **19200**

Replaces : **Bosch 0 272 220 827**

Unit-Numbers : **Bosch F 000 BL0 814, F 000 BL0 825, F 000 BL0 841, F 000 BL0 889, F 000 BL0 890, F 000 BL0 897, F 000 BL0 898, F 000 BL0 8A3, F 000 BL0 8A5, F 000 BL0 8A7, F 000 BL0 8D0, F 000 BL0 8D3, F 000 BL0 8E0, F 000 BL0 8F5; Lucas LRA03975; Nissan, Infiniti 23100-4BE0B, 23100-4BE0B-RP, 23100-4EA0A, 23100-4PA0A; Renault 23100-4PA0A, 231004BE0B**

IB835



Voltage Regulator - Bosch Replacement

Protocol : **LIN** ID : **16** COM Speed (bps) : **19200**


Replaces : **Bosch 0 272 220 835, Original Reference Number ARB6165**

Unit-Numbers : **Bosch 0 125 711 097, 0 125 711 098, 0 125 711 113, 0 125 711 114, 0 125 711 121, 0 125 711 122, 0 125 711 147, 0 125 711 148, 0 125 711 155, 0 125 711 156, 0 125 711 177, 0 125 711 178, 0 125 811 031, 0 125 811 032, 0 125 811 053, 0 125 811 054, 0 125 811 077, 0 125 811 078, 0 125 811 080, 0 125 811 119, 0 125 812 081, 0 125 812 082; Mercedes-Benz 000 906 05 04, 000 906 47 02, 0009062103, A 000 906 47 02, A0009060504, A0009062103**

LIN and BSS Voltage Regulators

www.waiglobal.com

IB840




Voltage Regulator - Bosch Replacement

Protocol : **LIN** ID : **8** COM Speed (bps) : **19200**

Replaces : **Bosch 0 272 220 810, 0 272 220 840, Original Reference Number ARB0840**

Unit-Numbers : **Bosch F 000 BL0 410, F 000 BL0 458, F 000 BL0 4C3, F 000 BL0 4C4, F 000 BL0 4DB; Dacia 23100-8386R, 23100-8593R; Mercedes-Benz 453-906-39-00, A453-906-39-00; Nissan, Infiniti 23100-3730R, 23100-4426R, 23100-6007R; 931365; Renault 23100-6007R, 23100-8593R, 231003730R**

IB855




Voltage Regulator - Bosch Replacement

Protocol : **LIN** ID : **40** COM Speed (bps) : **19200**

Replaces : **Audi, Volkswagen 03G 903 803 B, 03L 903 803 B, Bosch 0 272 220 805, 0 272 220 806, 0 272 220 825, 0 272 220 855**

Unit-Numbers : **Audi, Volkswagen 03L 903 023 M, 03L 903 024 F, 03L 903 024 FX, 04E 903 021 P, 04E 903 021 PX, 04E 903 023 D, 04E 903 023 DX, 04E 903 023 L, 04E 903 023 L, 04E-903-015-E, 04E-903-015-EX, 04L 903 023 T, 04L 903 023 T, 04L 903 023 TX, 04L 903 023 TX, 04L-903-023-J, 04L-903-023-JX; Bosch 0 125 811 004, 0 125 811 008, 0 125 811 026, 0 125 811 027, 0 125 811 028, 0 125 811 033, 0 125 811 035, 0 125 811 074, 0 125 811 088, 0 125 811 089, 0 125 811 090, 0 125 811 115, 0 125 811 116, 0 125 811 131, 0 125 811 132, 0 986 084 130; 286818, 931549**

IB867



Voltage Regulator - Bosch Replacement

Protocol : **LIN** ID : **88** COM Speed (bps) : **9600**

Replaces : **Bosch 0 272 220 867**

Unit-Numbers : **Bosch 0 125 711 131, 0 125 711 132, 0 125 711 133, 0 125 811 083, 0 125 811 084, 0 125 811 085, 0 125 811 086, F 000 BL0 6ET, F 000 BL0 6EY; Ford 1768612, BK2T 10300 DB, BK2T-10300-DB, BK3T-10300 -EB, BK3T-10300-EA, CC1T 10300 BD, CC1T-10300-BD, CC1T-10300-CB, CC1T-10300-CC, CC1T-10300-CD, CC1Z-10346-A**

IB885




Voltage Regulator - Bosch Replacement

Protocol : **LIN** ID : **24** COM Speed (bps) : **19200**

Replaces : **Bosch F 00M 144 157, F 00M 145 309, F 00M 145 377, F 00M 145 699, F 00M 145 885, Mercedes-Benz 003 154 43 06, 003 154 74 06, 003 154 99 06, 003-154-61-06, A 003 154 43 06, A 003 154 74 06, A 003 154 99 06, A 003-154-61-06**

Unit-Numbers : **Bosch 0 124 525 054, 0 124 525 055, 0 124 525 161, 0 124 525 195, 0 399 604 015; Marelli 063535250540; Mercedes-Benz 014-154-37-02, 272-154-00-02, 636-154-01-02, A014-154-37-02, A272-154-00-02, A636-154-01-02**

IB6088



Voltage Regulator - Bosch Replacement

Protocol : **BSS** ID : **1** COM Speed (bps) : **1200**


Replaces : **BMW 12-31-561-924, 12-31-561-939, Bosch F 00M 346 014, F 00M 346 025, F 00M 346 032, F 00M 346 088**

Unit-Numbers : **BMW 12-31-7-550-967, 12-31-7-550-967, 12-31-7-551-254, 12-31-7-551-254; Bosch 0 121 615 010, 0 121 615 110; Steyr 7550967**

LIN and BSS Voltage Regulators

www.waiglobal.com

IB818




Voltage Regulator - Bosch Replacement

Protocol : **LIN** ID : **120** COM Speed (bps) : **Auto Rate**

Replaces : **Bosch 0 272 220 818, F 00M 346 112**

Unit-Numbers : **BMW 12 31 7 628 243, 12 31 8 634 233, 123 8 614 277, 762824302; Bosch 0 125 813 002, 0 125 813 009, 0 125 813 013, 0 125 813 014, 0 125 813 015, 0 125 813 016, 0 125 813 023, 0 125 813 024**

IB828




Voltage Regulator - Bosch Replacement

Protocol : **LIN** ID : **88** COM Speed (bps) : **9600**

Replaces : **Bosch 0 272 220 828**

Unit-Numbers : **Bosch 0 125 812 013, 0 125 812 014, 0 125 812 017, 0 125 812 017, 0 125 812 018, 0 125 812 061, 0 125 812 062, 0 125 812 067, 0 125 812 068, 0 125 813 021, 0 125 813 022, 0 125 813 031, 0 125 813 032, 0 125 813 037, 0 125 813 038; Ford EJ32-10300-AC, EJ32-10300-AD; Jaguar 02T2H18581, 02T2H18582, 02T2H34202, EJ32-10300-AC, GX73-10300-CD, GX73-10300-CE, GX73-10300-DE, T2H18581, T2H18582; Land Rover EJ32-10300-AD, GX73-10300-CE, GX73-10300-DE, GX73-10300-DF, GX7310300DD, LR 105985, LR047579, LR070718, LR077394, LR079255, LR079256; Steyr GX7310300CE**

IM912




Voltage Regulator - Mitsubishi Replacement

Protocol : **BSS** ID : **167** COM Speed (bps) : **1200**

Replaces : **Mitsubishi 5805912C**

Unit-Numbers : **Citroen 5702J3, 5705KQ, V757595680, V75759568002, V758575080, V75857508001; Mitsubishi A005TG0881, A005TG0881ZE, A005TG0881ZEA, A005TG0881ZEB; Mitsubishi Sales A5TG0881, A5TG0881ZE, A5TG0881ZEA, A5TG0881ZEB; Original Reference Number V75769568001; Peugeot V75769568001**

IM404




Voltage Regulator - Mitsubishi Replacement

Protocol : **LIN** ID : **29** COM Speed (bps) : **Auto Rate**

Replaces : **Honda 31150-R1A-A01, Mitsubishi 667, 6671404J, 6673X12H, A866X66782**

Unit-Numbers : **Acura 31100-R1A-A01, 31100-R1A-A010M2, 31100-R1A-A01RM, AHGA81; Honda 06311-R1A-505RM, 31100-R1A-A01, 31100-R1A-A010M2, 31100-R1A-A01RM, AHGA81; Mitsubishi A005TJ0191, A005TJ0191ZC, A005TJ0191ZE, A5TJ0191AE; Mitsubishi Sales A5TJ0191, A5TJ0191ZC, A5TJ0191ZE**

IM624



Voltage Regulator - Mitsubishi Replacement

Protocol : **LIN** ID : **29** COM Speed (bps) : **Auto Rate**


Replaces : **Honda 31150-5A2-A01, Mitsubishi 7009Z18P**

Unit-Numbers : **Honda 31100-5A2-A02, 31100-5A2-A02RM, 31100-5A2-AA000M2, 31100-5B0-Y02, 31100-5B0-Y02RM, AHGA87, AHGA88; Mitsubishi A005TL0581, A005TL0581ZC, A5TL0591ZC; Mitsubishi Sales A5TL0581, A5TL0581ZC**



LIN and BSS Voltage Regulators

IM629




Voltage Regulator - Mitsubishi Replacement

Protocol : **LIN** ID : **45** COM Speed (bps) : **Auto Rate**

Replaces : **Mitsubishi 6954Z09L, 6955420L**

Unit-Numbers : **Ford 1741221, CJ5T-10300-CB, CJ5Z-10346-C; Mitsubishi A002TX2581, A002TX2581ZC; Mitsubishi Sales A2TX2581, A2TX2581ZC**

IN6370



Voltage Regulator - Denso Replacement

Protocol : **LIN** ID : **132** COM Speed (bps) : **9600**

Replaces : **Denso 126600-4110, 126600-4310, 4110, 4310, GC84110**

Unit-Numbers : **Denso 104210-2330, 104210-6540, 104210-6541, TN104210-2330; Ford CJ5T-10300-BB, CJ5T-10300-DB, CJ5T-10300-GA, CJ5Z-10346-A, CJ5Z-10346-D, CJ5Z-10346-F, GL-8785**

IN6373



Voltage Regulator - Denso Replacement

Protocol : **LIN** ID : **9** COM Speed (bps) : **19200**

Replaces : **Denso 126600-4360, 4360**

Unit-Numbers : **Denso 104211-3020, 104211-3021, 104211-3022, 104211-3290, 104211-3291, 104211-3293, 104211-3531; Toyota 27060-0V140, 27060-0Y130, 27060-36090**

IN6374



Voltage Regulator - Denso Replacement

Protocol : **LIN** ID : **28** COM Speed (bps) : **9600**

Replaces : **Denso 126600-3940**

Unit-Numbers : **Denso 104210-3551; Ford 3M5T-10300-JD; Volvo 8676015**

IN6376



Voltage Regulator - Denso Replacement

Protocol : **LIN** ID : **26** COM Speed (bps) : **Auto Rate**


Replaces : **Denso 126600-7511, 7511, IFX1 7511 03S14**

Unit-Numbers : **BMW 12-31-7-605-478, 12-31-7-605-478-02, 12-31-7-605-478-03, 12-31-7-605-480; Denso 104210-639, 104210-6390, 104210-6391, 104210-6392, 104210-6393, 104210-6394, 104210-6395; 554456RI, 931265**



LIN and BSS Voltage Regulators

IN7541




Voltage Regulator - Denso Replacement

Protocol : **LIN** ID : **50** COM Speed (bps) : **Auto Rate**

Replaces : **Denso 126600-7541, 7541**

Unit-Numbers : **BMW 12-31-7-606-628, 12-31-7-616-119, 12-31-7-616-121, 12-31-7-616-126, 7616119-01, 7616119-03, 7616119-04; Denso 104210-6440, 104210-6441, 104210-6442, 104210-6500, 104210-6501, 104210-6502, 104210-6503, 104210-6504, 104210-6510, 104210-6511, 104210-6512, 104210-6513, 104210-6514; 554478RI, 554480RI**

IN7720




Voltage Regulator - Denso Replacement

Protocol : **BSS** ID : **70** COM Speed (bps) : **1200**

Replaces : **Denso 126600-7720, 7720**

Unit-Numbers : **Denso 104210-6891; Porsche 7PP-903-016C, 7PP-903-016CX, T946015**

IN7740




Voltage Regulator - Denso Replacement

Protocol : **LIN** ID : **34** COM Speed (bps) : **Auto Rate**

Replaces : **Denso 126600-7740, 7740**

Unit-Numbers : **BMW 12-31-7-640-132, 12-31-7-640-875; Denso 104210-6720, 104210-6721**

IN8150




Voltage Regulator - Denso Replacement

Protocol : **LIN** ID : **33** COM Speed (bps) : **Auto Rate**

Replaces : **Denso 126600-8150, 8150**

IN3300



Voltage Regulator - Denso Replacement

Protocol : **LIN** ID : **28** COM Speed (bps) : **19200**


Replaces : **126600-3300**

Unit-Numbers : **DENSO 104210-1840, 104210-6080, 104210-6090, 104210-6590, 104210-6591, 104210-6592, TN104210-1840, TN104210-6592**

LIN and BSS Voltage Regulators

www.waiglobal.com

IN3570




Voltage Regulator - Denso Replacement

Protocol : **LIN** ID : **28** COM Speed (bps) : **9600**

Replaces : **Denso 126600-3570, 3570**

Unit-Numbers : **Denso 104210-1470, 104210-2420, 104210-2421, 104210-2422, 104210-5050, 104210-6120, 104210-6280, 104210-6360, 104210-6361, 104210-6420, 104210-6421, 104210-6480, 104210-6481, 104210-6482, 104210-6483; Ford 8W83-10300-BA, AH22-10300-AB; Jaguar 8X23-10300-BA, 8X23-10300-BB, 8X2310300CB, C2Z3414, C2Z3414E, C2Z3415; Land Rover BH42-10300-AC, BJ32-10300-AC, CPLA-10300-AB, CPLA-10300-AC, LR0-76696, LR011231, LR022528, LR034013, LR054994, LR055316, LR072764; Lucas LRA04134; AA7164**

IN4400




Voltage Regulator - Denso Replacement

Protocol : **LIN** ID : **132** COM Speed (bps) : **9600**

Replaces : **Denso 126600-4400, 4400**

Unit-Numbers : **Denso 104210-6620, DAN1203; Ford CX2310300AB, CX2310300AC, CX2310300AD; Jaguar C2Z18797**

IN7521




Voltage Regulator - Denso Replacement

Protocol : **LIN** ID : **50** COM Speed (bps) : **Auto Rate**

Replaces : **Denso 126600-7520, 126600-7521, 7520, 7521**

Unit-Numbers : **BMW 12-31-7-605-061, 12-31-7-605-479, 12-31-7-605-479, 7605061-06; Denso 104210-6400, 104210-6401, 104210-6402, 104210-6403, 104210-6406; Land Rover CPLA-10300-BD; 7605479, S7605061-02**

IN7630



Voltage Regulator - Denso Replacement

Protocol : **LIN** ID : **132** COM Speed (bps) : **9600**

Replaces : **Denso 126600-7630, 0122112212AA**

Unit-Numbers : **Denso 104210-1730, 104210-1731, 104210-1732, 104210-1971, 104211-3040, 104211-3041, 104211-3150, 104211-3151, 104211-3320, 104211-3330, MS104210-1971, MS104211-3330; Ford 1764816, 1781479, 1795985, 1821291, 1940809, CV6T-10300-BC, CV6T-10300-BE, CV6T-10300-FA, CV6T-10300-GA, CV6Z-10346-C; Ford Engineering CV6T-10300-DB, CV6T-10300-DC; 1940809, 554044RI, 554153RI, 931409**

M300



Voltage Regulator - Valeo Replacement

Protocol : **LIN** ID : **49** COM Speed (bps) : **Auto Rate**

Replaces : **Valeo 2617441, 599239**

LIN and BSS Voltage Regulators

www.waiglobal.com

M339




Voltage Regulator - Valeo Replacement

Protocol : **LIN** ID : **25** COM Speed (bps) : **Auto Rate**

Replaces : **Mercedes-Benz A0041543706, 1127-110RS, Valeo 599339**

Unit-Numbers : **Mercedes-Benz 0009060501, 014-154-12-02, 9060501, A0009060501, A00090605010080, A014-154-12-02; Valeo TG15C131, TG15C181**

M379



Voltage Regulator - Valeo Replacement

Protocol : **BSS** ID : **56** COM Speed (bps) : **1200**

Replaces : **Valeo 595379**

Unit-Numbers : **Mercedes-Benz A41 590 63500; Nissan, Infiniti 23100-0011R, 23100-0018R, 23100-0026R, 23100-8125R; f285772, 440217, 575920160; Renault 2310 000 26R, 231000018R, 7711368381, 7711497409, 8200 725 683, 8200 846 074, 8200 846 074, 8200 854 117, 8200747041, 8200854119; Valeo TG15C123, TG15C124, TG15C125, TG15C128, TG15C141, TG15C141, TG15C142, TG15C143, TG15C146**

M446



Voltage Regulator - Valeo Replacement

Protocol : **BSS** ID : **52** COM Speed (bps) : **1200**

Replaces : **BMW 8510087-01 , Valeo 593771, 595334, 595446**

Unit-Numbers : **BMW 12 31 8 507 623, 12 31 8 509 022, 12-31-7-516-490, 12-31-7-516-723, 12-31-7-516-724, 12-31-7-521-385, 12-31-7-522-962, 12-31-7-805-432, 12-31-7-808-073, 8507623, 8509022; Valeo FG18D024, FG18D057, FGN18D024, FGN18D057, SG14B017**

M464



Voltage Regulator - Valeo Replacement

Protocol : **BSS** ID : **57** COM Speed (bps) : **1200**

Replaces : **BMW 760377601, Valeo 595464**

Unit-Numbers : **BMW 12-31-4-595-890, 12-31-4-595-891, 12-31-7-575-344, 12-31-7-575-347, 12-31-7-603-779, 12-31-7-603-782, 12-31-7-807-187, 12-31-7-808-075, 12-31-8-507-625, 12-31-8-579-420; Valeo FG23S010, FG23S011, FG23S032, FG23S043, FG23S054**

M543



Voltage Regulator - Valeo Replacement


Protocol : **BSS** ID : **49** COM Speed (bps) : **1200**

Replaces : **Valeo 2543204, 2543231, 593877, 593983, 593984, 599102**

Unit-Numbers : **BMW 12-31-7-521-178, 12-31-7-524-972, 12-31-7-525-376, 12-31-7-525-440, 12-31-7-537-959, 12-31-7-537-962, 12-31-7-540-990, 12-31-7-540-992, 12-31-7-540-993, 12-31-7-540-994, 12-31-7-542-934, 12-31-7-542-935, 12-31-7-550-993, 12-31-7-561-003, 12-31-7-561-004, 12-31-7-792-878, 12-31-7-796-125, 12-31-7-797-523, 12-31-7-797-524, 12-31-7-801-173; 2586071; Valeo 2542720, 2542720F, 2543314A, TG17C015, TG17C016, TG17C016B, TG17C021, TG17C021B, TG17C027, TG17C027B, TG17C034, TG17C035, TG17C036**

LIN and BSS Voltage Regulators

M545



Voltage Regulator - Valeo Replacement

Protocol : **BSS** ID : **48** COM Speed (bps) : **1200**

Replaces : **Valeo 591901, 593796, 595200, 595265, 599101**

Unit-Numbers : **BMW 12-31-7-788-821, 12-31-7-789-981, 12-31-7-789-984, 12-31-7-797-204-AI02, 12-31-7-797-521, 12-31-7-797-521-AI01, 12-31-7-797-522, 12-31-7-799-204, 12-31-7-802-929, 12-31-7-834-160, 12-31-7-836-592, 12-31-8-517-261; Marelli 943390903630, 944390903630; Valeo 746135, TG17C010, TG17C010B, TG17C011, TG17C048**

M565



Voltage Regulator - Valeo Replacement

Protocol : **LIN** ID : **25** COM Speed (bps) : **Auto Rate**

Replaces : **Ford BA6T-10316-AA, IA7029OE, Valeo 595393, 599182, 599194, Volvo 30659440**

Unit-Numbers : **Bosch 0 986 083 620; Ford 1469714, 1506299, 1678607, 1678608, 1684713, 1685794, 1685794, 1704769, 1711969, 1763143, 1871861, 30285659, 7G9N-10300-CA, 7G9N-10300-CC, 8V21-10300-AB, 8V21-10300-BB, 9G9N-10300-CA, AG9T-10300-AA, AG9T-10300-BA, AG9T-10300-CA, AG9T-10300-DA, AV6N-10300-DA, AV6N-10300-DB, AV6N-10300-EA, AV6N-10300-HA, BV6N-10300-AA, BV6N-10300-BA, BV6Z-10346-G; Ford Engineering 7G9N-CC, 8V21-AB, 8V21-BB, AV6N-DA, AV6N-EA; Lucas LRA03555, LRA03555, LRA03885, LRA03885; Mazda Y405-18-300, Y406-18-300; 2543426A, 9214843; Valeo FG15T045, FG17T010, TG12C037, TG12C038, TG12C079, TG12C086, TG12C087, TG12C107, TG12C127, TG15C103, TG15C148, TG15C152, TG15C173, TG15C174, TG15C175, TG15C176; Volvo 31285436, 31285808, 36001101, 36002013**

M567



Voltage Regulator - Valeo Replacement

Protocol : **BSS** ID : **40** COM Speed (bps) : **1200**

Replaces : **Valeo 595318, 599149**

Unit-Numbers : **BMW 12-31-7-535-097, 12-31-7-535-098, 12-31-7-576-513, 12-31-7-576-514, 12-31-7-615-484; Citroen 7576513, 757651380; Peugeot 9664532780, V7576513; PSA Peugeot Citroen 5705 NR; Valeo 2605106A, 2605106B, TG12C039, TG12C059, TG12C061, TG12C061, TG12C120, TG12C120**

M568




Voltage Regulator - Valeo Replacement

Protocol : **LIN** ID : **17** COM Speed (bps) : **Auto Rate**

Replaces : **Valeo 593948, 593975, 595385**

Unit-Numbers : **Mercedes-Benz 266-154-06-02, 266-154-09-02, A266-154-06-02, A266-154-09-02, A2661541302; Valeo 2542774, 440410, TG11C021, TG11C035, TG11C074**

M571



Voltage Regulator - Valeo Replacement

Protocol : **BSS** ID : **44** COM Speed (bps) : **1200**


Replaces : **Hitachi 130633, Valeo 595252, 595253**

Unit-Numbers : **Bosch 0 986 084 100; Renault 7701477411, 7711368719, 8200 410 671, 8200 410 671-B, 8200 410 674, 8200 667 610, 8200410669, 8200410681, 8200561961, 8200588648, 8200622004, 8200623231, 8200667614, 8200667619, 8200718724; Valeo SG12B092, TG10B025, TG11C039, TG11C040, TG11C041, TG11C054, TG11C055, TG11C056, TG11C060, TG11C065, TG11C066, TG11C068, TG11C069**

LIN and BSS Voltage Regulators

www.waiglobal.com

M573




Voltage Regulator - Valeo Replacement

Protocol : **LIN** ID : **33** COM Speed (bps) : **19200**

Replaces : **Valeo 595243**

Unit-Numbers : Chrysler 04801250AA, 04801250AB, 04801250AC, 04801250AD, 4801250AA, 4801250AB, 4801250AC, 4801250AD, 5175765AA, 5175765AB; Mercedes-Benz 000-906-27-00, 642-154-02-02, 642-154-03-02, 642-154-04-02, 642-154-05-02, 646-154-01-02, A000-906-27-00, A642-154-02-02, A642-154-03-02, A642-154-04-02, A642-154-05-02, A646-154-01-02; Valeo 2542969C, 2542989C, TG17C028, TG17C030, TG17C030B, TG17C032, TG17C041

M573V1



Voltage Regulator - Valeo Replacement

Protocol : **LIN** ID : **33** COM Speed (bps) : **Auto Rate**

Replaces : **Valeo 2619624, 595325, 599317**

Unit-Numbers : Mercedes-Benz 646-154-11-02, A646-154-11-02; Valeo TG17C061

M575



Voltage Regulator - Valeo Replacement

Protocol : **BSS** ID : **53** COM Speed (bps) : **1200**

Replaces : **BMW 8510088-01, 8510089-01, Valeo 595212, 595348, 599095**

Unit-Numbers : BMW 12-31-7-79-05-48, 12-31-7-790-548, 12-31-7-795-620, 12-31-7-797-519, 12-31-7-797-520, 12-31-7-799-180, 12-31-7-799-181, 12-31-7-802-261, 12-31-7-802-471, 12-31-7-802-927, 12-31-7-803-724, 12-31-7-808-074, 12-31-7-823-291, 12-31-7-823-292, 12-31-8-507-624, 12-31-8-509-023, 12-31-8-509-739, 12-31-8-511-454, 12317802619, 7803724, 8507624; Bosch 0 986 080 580; 12090666, 553441RI, 9214841, 931268, AVA424; Valeo 2607239, 2607239B, 439723, 440313, A607239A, FG18S011, FG18S019, FG18S052, FG18S060, FGN18S011, FGN18S019, FGN18S052, FGN18S060, TG15C027, TG15C027B, TG15C073, TG15C093, TG15C157

M576



Voltage Regulator - Valeo Replacement

Protocol : **LIN** ID : **25** COM Speed (bps) : **19200**

Replaces : **Valeo 2543298, 593970**

Unit-Numbers : Mercedes-Benz 640-154-02-02, 640-154-03-02, 640-154-04-02, 640-154-05-02, 6401540102, A640-154-02-02, A640-154-03-02, A640-154-04-02, A640-154-05-02, A6401540102; Valeo TG15C034, TG15C056, TG15C057, TG15C057A, TG15C057B, TG15C057C, TG15C121

M583



Voltage Regulator - Valeo Replacement

Protocol : **LIN** ID : **49** COM Speed (bps) : **Auto Rate**

Replaces : **Valeo 599240**

Unit-Numbers : Citroen 5702J9, 5705KV, 96 780488 80, 96 780488 80, 98 030499 80, 98 105253 80, 98 105253 80; Peugeot 96 647796 80, 96 780488 80, 96 780488 80, 9678058680, 98 030499 80, 98 105253 80, 98 105253 80; PSA Peugeot Citroen 5702J9, 5702J9, 5705KV, 5705KV, 96 647796 80, 96 780488 80; Valeo TG15C135, TG15C189, TG15C194, TG15C195, TG15C211, TG15S205, TG15S218

LIN and BSS Voltage Regulators

M584




Voltage Regulator - Valeo Replacement

Protocol : **LIN** ID : **25** COM Speed (bps) : **Auto Rate**

Replaces : **Valeo 2627666**

Unit-Numbers : Ford 1703864, 1704769, 1857696, 1873207, AE8T-10300-AA, AE8T-10300-BA, AV6N-10300-DC, AV6N-10300-GB, AV6N-10300-GC, BE8Z-10346-A, BV6N-10300-DB, BV6T-10300-EA, BV6T-10300-EB, BV6Z-10346-E, BV6Z-10346-F, CV6Z-10346-B, FV4T-10300-MA, FV4T-10300-MB; Mazda Y66618300A; 210708001341, 220721040950; Valeo 2610970A, FG12S027, FG15S046, FG15S046SP, FG15S065, FG15S065SP, FG15S091, FG15S091SP, FG15S109, FG15T093, FGN15S109, TG12C098, TG12C108, TG12C122, TG15C169, TG15C183; Volvo 30659389, 31285658, 36001502, 36001971

M586



Voltage Regulator - Valeo Replacement

Protocol : **BSS** ID : **52** COM Speed (bps) : **1200**

Replaces : **1127-095RS, Valeo 595416**

Unit-Numbers : 1017-163RS, 12046440, 12090369, 553245RI, 553994RI, 9213858, AVA321, L 46 440; Renault 8200634135, 8200654541; Valeo TG9B041, TG9B042, TG9B107

M591



Voltage Regulator - Valeo Replacement

Protocol : **LIN** ID : **49** COM Speed (bps) : **Auto Rate**

Replaces : **Valeo 595291, 599171, 599296**

Unit-Numbers : Chrysler 68022877AA, 68022877AB; Mercedes-Benz 000 906 34 22,000-906-35-22,642-154-08-02, 646-154-08-02, A 000 906 34 22, A-000-906-35-22, A642-154-08-02, A646-154-08-02; Valeo 2614306B, 440463, TG23C017, TG23C019, TG23C034, TG23C035

M594



Voltage Regulator - Valeo Replacement

Protocol : **LIN** ID : **41** COM Speed (bps) : **Auto Rate**

Replaces : **Original Reference Number 1127-115RS, Valeo 2614021, 2619228, 599187**

Unit-Numbers : Citroen 9678058480; 57266, 59213689, 930597, AVA471, EF37950, L 81 150, L 81 151; Peugeot 5702-J4, 5705-KR, 9678049480, 9803750980; Valeo 439932, 440676, FG18S095, FG18T106, FG18T112, FGN18S095, FGN18T106, FGN18T112

M595



Voltage Regulator - Valeo Replacement

Protocol : **LIN** ID : **169** COM Speed (bps) : **Auto Rate**

Replaces : **BMW 8515518-01, Valeo 599212**

Unit-Numbers : BMW 12 31 7 823 343, 12 31 8 509 224, 12 31 8 509 225, 7 823 343; Valeo FG18S045, FG18S066, FGN18S045, FGN18S066

LIN and BSS Voltage Regulators

www.waiglobal.com

M596



Voltage Regulator - Valeo Replacement

Protocol : **LIN** ID : **161** COM Speed (bps) : **Auto Rate**

Replaces : **Valeo 599228**

Unit-Numbers : **BMW 12-31-7-823-344, 12-31-8-519-890, 12-31-8-519-891, 8-519-890;Valeo FG18D111,FGN18D111**

M597



Voltage Regulator - Valeo Replacement

Protocol : **BSS** ID : **36** COM Speed (bps) : **1200**

Replaces : **Valeo 593536, 593833**

Unit-Numbers : **BMW 12-31-7-505-898, 12-31-7-505-902, 12-31-7-516-107, 12-31-7-516-108, 12-31-7-519-621, 12-31-7-519-622; Valeo SG9B040, SG9B050, SG9B052**

M600




Voltage Regulator - Valeo Replacement

Protocol : **BSS** ID : **48** COM Speed (bps) : **1200**

Replaces : **Audi, Volkswagen 059903803G, Valeo 2608220, 591800, 593918, 593987, 595457, 595458**

Unit-Numbers : **Audi, Volkswagen 021-903-016, 021-903-016X, 03G-903-016A, 03G-903-016AX, 059-903-015R, 059-903-015RX, 059903015RX, 06C-903-016H, 06C-903-016HX, 06C-903-016J, 06C-903-016JX, 06E-903-016C, 06E-903-016D, 06E-903-016DX, 06E-903-016F, 06E-903-016FX, 06E-903-016G, 06E-903-016K, 06E-903-016KX; Porsche 955-603-117-00; Valeo TG16C010, TG16C012, TG16C014, TG17C020, TG17C022, TG17C023, TG17C024, TG17C024 SP, TG17C039, TG17C040, TG17C044, TG17C054, TG17C056, TG17C065, TG17C072**

M601



Voltage Regulator - Valeo Replacement

Protocol : **LIN** ID : **41** COM Speed (bps) : **Auto Rate**

Replaces : **Audi,Volkswagen 06E 903 803 N,079 903 803 F,Mercedes-Benz A0041541706,Valeo 2543589,2610921, 2613952, 595371, 599103, 599161, 599213, 599235, 599241**

Unit-Numbers : **Audi, Volkswagen 021-903-016L, 021-903-016LX, 03H-903-023C, 03H-903-023CX, 059 903 019 D, 059-903-016Q, 079-903-015F, 079-903-015FX; Bosch 0 986 083 660; Mercedes-Benz 000 906 27 00, 000 906 79 00, 000-906-75-00, 013-154-68-02, 013-154-68-02-0080, 014-154-04-02, 014-154-28-02, A 000 906 27 00, A 000 906 79 00, A-000-906-75-00, A0009093622, A0131546802, A01315468020080, A014-154-04-02, A014-154-28-02; Original Reference Number 9215227; Valeo FG18S012, FG18S013, FG18S016, FG18S036, FG18S040, FG18S043, FG18S044, FG18S056, FG18S077, FG18S078, FG18S100, FG18T070, FGN18S012, FGN18S013, FGN18S016, FGN18S036, FGN18S040, FGN18S043, FGN18S044, FGN18S056, FGN18S077,FGN18S078, FGN18S100**

M603



Voltage Regulator - Valeo Replacement

Protocol : **LIN** ID : **25** COM Speed (bps) : **19200**


Replaces : **Valeo 599119, 599340**

Unit-Numbers : **Audi, Volkswagen 03C-903-023T, 03C-903-023TX, 03D-903-025M, 03D-903-025MX, 03L-903-023A, 03L-903-023AX, 03P-903-023A, 03P-903-023B, 03P-903-023BX, 059 903 016 G, 06H-903-017E, 06H-903-017EX, 06H-903-023-E, 06H-903-023-EX, 06J-903-023-N, 06J-903-023-NX; Bosch 0 986 083 530; A609874A; Valeo 2611257A, TG14C019, TG14C022, TG14C028, TG14C031, TG14C035, TG14C037, TG14C039**

LIN and BSS Voltage Regulators

www.waiglobal.com

M609




Voltage Regulator - Valeo Replacement

Protocol : **LIN** ID : **9** COM Speed (bps) : **Auto Rate**

Replaces : **Valeo 599260**

Unit-Numbers : Dacia 23100-7842R, 23100-7842RA; Nissan, Infiniti 23100-4BA0A, 23100-4BA0B, 23100-7842R; Renault 23100-7842R, 23100-7865R, 231000643R; Valeo TG12C124, TG12C125, TG12C152

M610




Voltage Regulator - Valeo Replacement

Protocol : **LIN** ID : **41** COM Speed (bps) : **19200**

Replaces : **13075, C758787B2025E, Valeo 599125**

Unit-Numbers : Lucas LRA03326; Mercedes-Benz 000-906-21-00, 000-906-36-22, 000-906-86-01, 014-154-09-02, 014-154-33-02, A-000-906-21-00, A-014-154-33-02, A000-906-86-01, A0009063622, A014-154-09-02; 9215227; Valeo 2605594B, 2614200, FG18S029, FG18S032, FG18S061, FG18S098, FGN18S032, FGN18S061, FGN18S098

M620




Voltage Regulator - Valeo Replacement

Protocol : **LIN** ID : **89** COM Speed (bps) : **Auto Rate**

Replaces : **Audi, Volkswagen 059 903 803 N, Valeo 599237**

Unit-Numbers : Audi, Volkswagen 03L 903 017B, 03L 903 017BX, 04L 903 017A, 059-903-018QX, 059903018Q, 059903018QX, 06E-903-018L, 06E-903-018LX, 06H-903-017K, 06H-903-017KX, 06H-903-018M, 06H-903-018MX; Lucas LRA03392; Valeo FG20S015, FG20S016, FG20S017, FG20S018, FG20S019, FG20S022, FGN20S016, FGN20S018, FGN20S019, FGN20S022

M636




Voltage Regulator - Valeo Replacement

Protocol : **LIN** ID : **17** COM Speed (bps) : **Auto Rate**

Replaces : **Mercedes-Benz A0041542806, Valeo 599304**

Unit-Numbers : Mercedes-Benz 014-154-14-02, 271-154-14-02, 639-150-02-50, 639-150-03-50, A014-154-14-02, A014-154-14-02-80, A271-154-14-02, A639-150-02-50, A639-150-03-50; Mitsubishi Motors 1800A029; Valeo TG11C036, TG11C059, TG12C026, TG12C063

M646



Voltage Regulator - Valeo Replacement


Protocol : **BSS** ID : **56** COM Speed (bps) : **1200**

Replaces : **BMW 7536660, IA4642OE, Valeo 593780, 593873, 593986**

Unit-Numbers : BMW 12-31-7-521-135, 12-31-7-521-136, 12-31-7-521-137, 12-31-7-521-138, 12-31-7-800-308, 12-31-7-802-928, 12-31-7-836-610, 12-31-7-837-691; Mercedes-Benz 271-154-09-02, A271-154-09-02; 2586077; Valeo 2542582B, SG12B062, TG15C018, TG15C018B, TG15C072, TG15C098

LIN and BSS Voltage Regulators

M647



Voltage Regulator - Valeo Replacement

Protocol : **LIN** COM Speed (bps) : **19200**

Replaces : **Mercedes-Benz A0031547806, Valeo 595387**

Unit-Numbers : **Mercedes-Benz 014 154 15 02, 271-154-15-02, A 014 154 15 02, A271-154-15-02; Valeo TG15C075, TG15C133**

M648




Voltage Regulator - Valeo Replacement

Protocol : **BSS** ID : **35** COM Speed (bps) : **1200**

Replaces : **BMW 7603775-01, Hitachi 130644, Valeo 591894, 595365, 599232**

Unit-Numbers : **BMW 12-31-7-533-469, 12-31-7-560-988, 12-31-7-560-989, 12-31-7-573-754, 12-31-7-573-755, 12-31-7-603-778, 12-31-7-801-124, 12-31-7-804-266, 7-533-469; Bosch 0986083460; 4538532, S29AN07; Valeo TG23C011, TG23C012, TG23C013, TG23C018, TG23C033**

M652




Voltage Regulator - Valeo Replacement

Protocol : **LIN** ID : **17** COM Speed (bps) : **Auto Rate**

Replaces : **Valeo 599271**

Unit-Numbers : **Nissan, Infiniti 23100-08633R, 23100-4BE0B, 23100-8633R; Opel 1202452, 4407989; AA7892; Renault 23100-7281R; Valeo FG15T057, FG15T071; Vauxhall 93868641, 9551988, 95519888**

M183



Voltage Regulator - Valeo Replacement

Protocol : **LIN** ID : **49** COM Speed (bps) : **19200**

Replaces : **Audi, Volkswagen 059 903 803 L, Valeo 599183**

Unit-Numbers : **Audi, Volkswagen 059-903-019, 059-903-019X; Valeo FG23S061, FGN23S061**

M256



Voltage Regulator - Valeo Replacement

Protocol : **BSS** ID : **44** COM Speed (bps) : **1200**

Replaces : **Valeo 593816, 595256**

Unit-Numbers : **BMW 12-31-7-521-382, 12-31-7-521-489, 7521382-02; Valeo SG11B010**

LIN and BSS Voltage Regulators

M296




Voltage Regulator - Valeo Replacement

Protocol : **LIN** ID : **49** COM Speed (bps) : **Auto Rate**

Replaces : **Valeo 599296**

Unit-Numbers : **Chrysler 68022877AA, 68022877AB, Valeo TG23C017, TG23C019, TG23C034, TG23C035**

IH789




Voltage Regulator - Hitachi Replacement

Protocol : **BSS** ID : **105** COM Speed (bps) : **1200**

Replaces : **Hitachi 1178**

Unit-Numbers : **Hitachi LR1190-905**

IH791



Voltage Regulator - Hitachi Replacement

Protocol : **BSS** ID : **105** COM Speed (bps) : **1200**

Replaces : **Hitachi 1194**

Unit-Numbers : **Hitachi LR1190-924**

M154




Voltage Regulator - Valeo Replacement

Protocol : **BSS** ID : **47** COM Speed (bps) : **1200**

Replaces : **Valeo 599154**

Unit-Numbers : **Citroen 5705JG, 9666998080; PSA Peugeot Citroen 96 669979 80; Valeo FG15T044, FG15T072**

M173



Voltage Regulator - Valeo Replacement

Protocol : **BSS** ID : **34** COM Speed (bps) : **1200**


Replaces : **Valeo 599173**

Unit-Numbers : **Nissan, Infiniti 23100-7033R; Renault 23100-4554R; Valeo FG15T030, FG15T056**

LIN and BSS Voltage Regulators

www.waiglobal.com

M233




Voltage Regulator - Valeo Replacement

Protocol : **LIN** ID : **25** COM Speed (bps) : **Auto Rate**

Replaces : Mercedes-Benz A0041542906, Valeo 595332, 599211, 599233, 599276, 599302

Unit-Numbers : Audi, Volkswagen 039-903-016G, 03H-903-023E, 03H-903-023EX, 03H-903-023L, 03H-903-023LX, 03L-903-023L, 03L-903-023LX, 03L-903-024-D, 03L-903-024-T, 03L-903-024M, 03L-903-024MX, 04C-903-023K, 04C-903-023KX, 04E-903-023K, 04E-903-023KX, 04L-903-021-D, 04L-903-023-L, 06E-903-016Q, 06E-903-016QX, 06J-903-023-R, 06J-903-023H, 06J-903-023HX, 06J-903-023Q, 06J-903-023QX, 06J-903-023RX, 06K-903-015X; Mercedes-Benz 0009060401, 9060401, A 000 906 04 01, A 014 154 11 02, A0009060401; Valeo 439671, 440257, TG14C018, TG14C020, TG14C041, TG14C043, TG14C044, TG14C046, TG14C049, TG14C051, TG14C054, TG14C055, TG14C056, TG14C057, TG14C058, TG14C059, TG14C060, TG14C067, TG14C071, TG14C078, TG14C097, TG15C130, TG15C182

M234




Voltage Regulator - Valeo Replacement

Protocol : **LIN** ID : **33** COM Speed (bps) : **Auto Rate**

Replaces : Valeo 2543587, 595305, 599234

Unit-Numbers : Audi, Volkswagen 03G-903-016F, 03G-903-016FX, 059 903 019C, 059 903 019CX, 059-903-016G, 059-903-016GX, 059-903-016J, 059-903-016JX, 06D-903-016D, 06D-903-016DX, 06E-903-016S, 06E-903-016SX, 06E-903-018E, 06H-903-017-S, 06H-903-017-SX; Fiat 51880175; 89214394; Valeo 2543397, 440211, TG12S111, TG14C042, TG14C047, TG15C094, TG15C095, TG15C144, TG15C145, TG15C149, TG15C190, TG15C196

M236




Voltage Regulator - Valeo Replacement

Protocol : **LIN** ID : **73** COM Speed (bps) : **Auto Rate**

Replaces : Valeo 599236

Unit-Numbers : Audi, Volkswagen 03H-903-023J, 03H-903-023JX, 03L 903 024 L, 03L903023N, 03L903023NX, 03L903024LX, 04E-903-021Q, 04E-903-021QX, 04E-903-023M, 04E-903-023MX, 059-903-023M, 059-903-023MX, 06E-903-023C, 06H-903-017D, 06H-903-017DX, 06J-903-023K, 06J-903-023KX, 6H903017D, 6H903017DX; 12090416, 553456RI, 930956, AVA541; Valeo 286703, 286739, 439835, 439840, 440327, 440560, 440565, 440674, 931413, FG18T063, FG18T079, FG18T084, FG18T101, FG18T119, FG18T120, FG18T121, FG18T122, FG18T123, FG18T142, FGN18T063, FGN18T079, FGN18T084, FGN18T101, FGN18T119, FGN18T120, FGN18T121, FGN18T122, FGN18T123, FGN18T142

IN6325




Voltage Regulator - Denso Replacement

Protocol : **BSS** ID : **70** COM Speed (bps) : **1200**

Replaces : Denso 126600-7310, 126600-7420, 7310, 7420, Original Reference Number 742004L06

Unit-Numbers : BMW 12-31-7-550-468-01, 12-31-7-550-468-02, 12-31-7-552-815, 12-31-7-552-816, 12-31-7-591-268, 12-31-7-591-271, 12317550468; Denso 104210-6020, 104210-6021, 104210-6022, 104210-6040, 104210-6250, 104210-6251, 104210-6254; AA6607

IN6363



Voltage Regulator - Denso Replacement

Protocol : **LIN** ID : **244** COM Speed (bps) : **19200**

Replaces : Denso 126600-3970, GC83970


Unit-Numbers : Acura 31100-5X6-J01, 31100-5X6-J01RM, 31100-RX0-A01, 31100-RX0-A01RM; Denso 104210-1490, 104210-1530, 104210-1650, 104211-3470, 104211-8280, MS104211-8280; Honda 31100-5J0-A01, 31100-5J0-A01RM, 31100-5X6-J01, 31100-5X6-J01RM, 31100-R3L-G01, 31100-RSX-G01, 31100-RX0-A01, 31100-RX0-A01RM, CSJ49, CSJ65, CSK28, CSP47



LIN and BSS Voltage Regulators

www.waiglobal.com

IN6367



Voltage Regulator - Denso Replacement

Protocol : **BSS** ID : **70** COM Speed (bps) : **1200**

Replaces : **Denso 126600-7390, 7390**

Unit-Numbers : **BMW 12-31-7-591-529, 12-31-7-591-530, 7591529-02, 7591529-03; Denso 104210-6070, 104210-6071, 104210-6072**

NEW WAI1000 Tester

 The Power of WAI

Features

- Automatically detects protocol version, baudrate
- Besides LIN and BSS it will support:
 - SIG: Ford, Mazda
 - Land Rover plus FR: current usage of alternator
 - PD: Mazda old type
 - RLO: Denso types for Toyota plus FR
 - L-RVC: General Motors plus FR
 - C: Denso and Mitsubishi plus FR
- DFM monitor
- Feedback on unsupported regulators
- Indication of enhanced checksum support of regulator
- Information about class and vendor of regulator
- Fluent voltage regulator
- Option to test on car
- Option to detect surge between com line and B+
- Does not require voltage meter to show read voltage
- Support for larger amount of LIN regulators



Call us now for price and availability



China
WAI China - Shanghai
Building No. 36 | 215 De
Bao Rd Wai Gao Qiao
Free Trade Zone
Pudong, Shanghai 200131

USA
WAI Corporate Florida
3300 Corporate Way
Miramar, FL 33025

Europe
WAI Europe - Netherlands
Klappolder 225
2665 MR Bleiswijk, The Netherlands

1.800.877.3340

www.waiglobal.com



TRANSPO 